

SuperLite

CARE INFORMATION

WWW.SAFTI.COM 888.653.3333

SuperLite[®]

CARE INFORMATION

DO

- Start cleaning at the top of the building working down.
- When cleaning, make certain to use a non-abrasive, commercial window cleaning solution.
- Soak the glass surface with a clean water and soap solution to loosen dirt and debris.
- Dry all cleaning solution from the window.
- Clean one window first to see if the cleaning method caused any damage.
- Prevent conditions that can damage the glass.
- Avoid cleaning tinted and coated glass surfaces in direct sunlight.

DO NOT

- Use any type of scrapers for cleaning glass.
- Allow dirt and residue to remain on the glass for an extended time.
- Leave water or cleaning residue on glass or adjacent materials.
- Begin cleaning until all dirt and debris has been removed with a clean water and soap solution.
- Use abrasive cleaning solutions or materials; only use a mild, non-abrasive window cleaning solution.
- Allow metal parts of cleaning equipment to come in contact with the glass.
- Trap abrasive particles between the cleaning materials and the glass.
- Allow splashed materials to dry on glass.
- Allow conditions that can damage the glass.
- Allow other materials that can come in contact with the glass.
- Begin cleaning the glass without making sure that a coated surface is not exposed.

Failure to comply with the SAFTI *FIRST* recommended care and cleaning procedures may result in a void warranty. For questions or more information, please call 888.653.3333